


Map 28. Alterations of River Morphology - Current Situation 2015

Updated ITRBMP 2019



This map illustrates full water bodies which are affected by morphological alterations. The exact locations of individual water body alterations are not visualised.

This map is based on national information provided by the Tisza countries (HU, RO, RS, SK, UA), except for the following: EuroGlobalMap v2.1 from EuroGeographics was used for national borders of HU, RO, SK and UA; Shuttle Radar Topography Mission (SRTM) from USGS Seamless Data Distribution System was used as topographic layer.

www.interreg-danube.eu/jointisza